

Tuesday, May 05, 2026

09:00 – 09:15	Welcome & Introduction <ul style="list-style-type: none">▪ Overview of seminar objectives
09:15 – 10:45	<ul style="list-style-type: none">▪ Qualification Document Types▪ Structure of Qualification Documents
10:45 – 11:00	Coffee Break
11:00 – 12:30	AP Connect
12:30 – 13:30	Lunch Break
13:30 – 14:30	Group Work Session 1 <ul style="list-style-type: none">▪ AP Connect in the Showroom▪ Qualification Examples<ul style="list-style-type: none">▪ According to ISO 17025▪ T-Check Abbemat▪ Documentation▪ Measuring equipment
14:30 – 14:45	Coffee Break
14:45 – 15:45	Group Work – Session 2 <ul style="list-style-type: none">▪ Group Rotation
15:45– 16:00	Short Break
16:00 – Open End	Q&A Session